		EV	ENT ANA	LYSIS REPORT				
UNIT NO: 04	04 TPS: Khaperkheda TPS Unit Capacity: 210 MW							
1. *HO Code :	Station Code : T003	Tim 02:20		<b>Date -</b> 29/12/2017		<b>No. of days from last sync.:</b> 7 days		
2. Operating co	onditions at the tin	ne of Eve		in 4.1				
Load		Coal Cycles in service			Oil Support			
160 MW		-	A, B, C, E & F			NIL		
3. Nature of Ev	ent: TA set tripped d	ue to "Furr	nace Pressi	ıre Very High".			*	
4. Name of Firs	st Up , Main Protecti	ons & Pro	tection on	which GCB tripp	ped:			
	sure Very High (First							
	ons: On dt. 29/12/201							
	D Standby). Due to fa							
	ery High" protection.				ened o	n reverse power	r protection.	
5 B) Remedial A	Action/work done: 1	No specific	work done	2.				
6. Root Cause A	nalysis: Due to fallin	g of clinke	r, furnace o	lraft disturbed an	d boile	er tripped on 'fu	rnace pressure very	
high' protecti								
7. Preventive a	ction suggested (Sho	ort Term):						
O Dwarrantirra a	ation suggested (Lov	ng Town) .					*	
8. Preventive a	ction suggested (Lo	ng Term):						
9. Similar event occurred last time :			Unit No # 4, 210 MW Time		e:: 22:57 Hrs. Date: 21/12/2017			
	tripped on "Furnace l		ery High".					
	ns: No specific work			i <sup>l</sup>				
	ation Status of Long	Term/Sho			at Sir			
10. Boiler lighted up			Time - 03:37Hrs		Date - 29/1			
11. T-A Set Synchronized			Time -	<b>Time</b> - 05:49Hrs			<b>Date</b> - 29/12/2017	
12. Remark:		4						
							Liny.	
						1	Chief Engineer	
13. Recommend	dations of Works Se	ction:						
1. Procure	ment/Replacement	Plan:						
	onal Error:							
	Maintenance:							
	bringing back the U	nit:						
5. Training								
	remedial action is	completed	l satisfact	ory & point is clo	sed:			
				V		C E.	/Dv C E (Works)	