	T I	EVENT ANALYS	SIS REPORT		
UNIT NO: 02 TPS: Khaperkheda TPS Unit Capacity: 210 MW					
1. *HO Code :	Station Code: T00	Time – 23:46Hrs	<b>Date -</b> 05/07/2016	No. of days from last sy 43 days.	nc.:
2. Operating co	nditions at the time	e of Event :			
I	oad	Coal Cycles	in service	Oil Support	
90 MW		A 8	& B	Nil	
3. Nature of Eve	nt: Set withdrawn du	e to "Zero Scheduling	g" given by MSLDC.		
4. Name of First Up, Main Protections & Protection on which GCB tripped:  Hand Tripped [First Up], Generator Protection Operated, Generator Reverse Power Protection Operated,  AVR PT Fuse Failure, Class – "A" & "C" Lock out Relay Operated.					
dt.06/07/16 service. Load	s: MSLDC requested b of the one of the one of the one of the one of the one of the one of the one of the one of the one of the one of the one of the one o	.00 hrs. set was on lo	ad at 165 MW with fi	g" from 00.00 hrs on ve coal cycles (E – Standby) ir ly, set withdrawn at 23.46 hr	ı s on
5B) Remedial Action/Work done: No specific work done.					
6. Root Cause Analysis: Set under shutdown due to low system demand.					
7. Preventive action suggested (Short Term) :-					
8. Preventive action suggested (Long Term):-					
		*			
9. Similar event	occurred last time:-	Unit No #	Time · F	Trs Date	
Event: No similar event found. Remedial Actions:					
9A. Implementat	ion Status of Long Te	erm/Short Term me	asures stated at Sr.	No 7 & 8 :-	
10. Boiler lighte	ed up	Time - 17:	15 Hrs	Date - 22/08/2016	
11. T-A Set Sync	hronized	Time - 04:	44 Hrs	<b>Date -</b> 23/08/2016	
12. Remark :		*	y		
			C	Rg   9 hief Engineer	
13. Recommenda	ntions of Works Secti	on:		Zinginicu	
1. Procurement/	Replacement Plan:				
2. Operational Er		7			
3. Delay in Maint					
4. Delay in bringi					
5. Training of Sta		1	9		
	dial action is comple	ted satisfactory & n	oint is closed:		
		J - F		C E/Dy C E (Works)	