EVENT ANALYSIS REPORT								
UNIT NO: 04	NO: 04 TPS: Khaperkheda TI		S Unit Capa			acity : 210 MW		
1. *HO Code :	Station Code :	Tim	me - Date - .7 Hrs 09/05/2016		1	No. of days from last sync. : 48 days		
	T003	10:17			4			
2. Operating conditions at the time of Event :-								
Load		(	Coal Cycles in service			Oil Support		
185 MW			A, C, D, E, F			NIL		
3. Nature of Event: TA set tripped due to furnace pressure very low.								
4. Name of First Up, Main Protections & Protection on which GCB tripped:								
Boiler Trip. (First Up), Turbine Tripped, MFT Operated.								
5 A) Observations: - On Dt.09/05/2016, Set was on load at 185 MW with A, B, C, D, E and F coal mills in								
service. Consequent upon sudden falling of a large clinker disturbance occurred in furnace draft which								
led to boiler tripping on 'Furnace Pressure Very Low' protection. This resulted in set tripping on boiler interlock at 10:17 Hrs on date 09/05/16.								
5 B) Remedial Action/work done: - No specific work carried out.								
6. Root Cause Analysis: - Due to falling of clinker, furnace draft disturbed and set tripped due to furnace								
pressure very low. It is suspected that clinker formation might be due to very poor quality of coal.								
7. Preventive action suggested (Short Term):-								
8. Preventive action suggested (Long Term) :-								
9. Similar event occurred last time:-					Time:		Date:	
		me:-	Unit No # 4, 210 MW		1	15:59 Hrs 02/02/2016		
<b>Event:</b> Boiler tripped on "Furnace Pressure Very Low" which resulted in set tripping on boiler interlock.								
Remedial Actions: - No work done.								
9A. Implementation Status of Long Term/Short Term measures stated at Sr No 7 & 8:-								
10. Boiler lighted up			Time - 10:47 Hrs		Date- 09/05/2016			
11. T-A Set Synchronized Time - 13:43 Hrs Date- 09/05/2016								
12. Remark:-								
AP v.								
-	Chief Engineer							
13. Recommendations of Works Section:								
1. Procurement/Replacement Plan:								
2. Operational Error:								
3. Delay in Maintenance:								
4. Delay in bringing back the Unit:								
5. Training of Staff:								
	remedial action	is comple	eted satis	sfactory & point	is clo	osed:		
		•		× A		C E/Dy C E (W	Vorks)	