		EVE	NT ANAL	YSIS RE	PORT			
UNIT NO: 01	TIDE VI II I TOO					Unit Capacity : 210 MW		
1. *HO Code:	Station Code: T003		Time - 01:13 H		Date - 23/06/2015		No. of days from last sync. : 15 days	
2. Operating conditions at the time of Event :-								
Loa	Coal Cycles in service				Oil Support			
50 MW			A				Nil	
3. Nature of Event: Boiler Steaming Valid	lity expired on 01-07	-15.				N/A due	to PA Fan Problems &	
4. Name of First Up Flame Failure (First I	Up), Turbine Trip, Tı	ırbine tr	ip gear op	erated,	Gen. Prot. Operat	ed, GCB o	pened on RPP	
5A) Observations:to PA Fan Problems &5 B) Remedial Action	T.A. Set withdrawn as Boiler Steaming Validary Nork done: rawn on 23-06-15 to refitting & 1D Impel & 1F bearing inspections of Lub Oil DE / NDE Bearing / Exteristics taken & LP Interior of Lub Oil Control of Lub Oil DE / NDE Bearing / Exteristics taken & LP Interior of Lub Oil Control of Lub Oil DE / NDE Bearing / Exteristics taken & LP Interior of Lub Oil	carry ou ler repla on / rep System Housing Bypass o	Hrs on 23 s expired of the Preparate aced. DE & blacement for PA Faireplaced.	-06-15 on 01-0 tory wo NDE be carried n 1B & 1 PA Fan	to avoid Heavy Fu 7-15. rk for Statutory H earing replaced fo out. ID carried out. 1C motor decoupl	uel Oil Co ydraulic r both Fa	ns. as C/m-B,C,D N/A due Test carried out on 26- n.	
6. Root Cause Analysis: - Boiler Steaming Validity Extension as steaming validity was expired on 01-07-15.								
7. Preventive action suggested (Short Term):-								
8. Preventive action suggested (Long Term):-								
9. Similar event occu	ırred last time:-	Unit	No # 1, 2	10MW	Time: 03:2	6 Hrs	Date: 11/05/12	
Remedial Actions: TM: Work related to S BM: 1> C/m-1A -> Pre 2> C/m-1D -> Pre 3> C/m-1E -> Pre		arried o anical fac r Box oil anical fac	ut. Separa ce Seal ser filtration. ce Seal ser	te Shee	t is attached. & Gear Box oil filtr	ation.	nge ,Coal Mill Maint.	
EM: C/c-1F, AC Scann	ier, Motor, AVR Filter	cleaning	replaceme g, Seal Air	ent. Fan Mo	tor (A.B.C) Prever	itive Mair	nt were carried out	
9A. Implementation	Status of Long Term	/Short	Term mea	asures	stated at Sr No 7	& 8 :-	it. Were carried out.	
10. Boiler lighted u	p		Time -				- 27/06/2015	
11. T-A Set Synchron	nised		Time -	10:19	Hrs		- 27/06/2015	
12. Remark :-						Chief	Acallia - Engineer	
13. Recommendation	s of Works Section:					Giffel		
1. Procurement/Repl	lacement Plan:							
2. Operational Error:				10.0				
3. Delay in Maintenar	ice:							
4. Delay in bringing b								
5. Training of Staff:								
6. Whether remedial	action is completed	satisfac	tory & no	intico	losed:			
	7		, a po			C E /Dv.	CE (Works)	
						C E/Dy	CE (Works)	