EVENT ANALYSIS REPORT							
UNIT NO: 03	TPS: Khape	ΓPS		U	Unit Capacity: 210 MW		
1. *HO Code :	Station Code :	Т003	Time –	Date -	No	of Days from last sync. :	
1. "NO Code:	Station code.		13:23 Hrs	03/03/201	8 9 d	9 days	
2. Operating conditions at the time of Event :-							
Load		C	Coal Cycles in service			Oil Support	
89 MW		C & D			Nil		
3. Nature of Event: T.A. Set withdrawn as per directives of ED (O&M).							
4. Name of First Up, Main Protections & Protection on which GCB tripped: Flame Failure (First Up), Loss Of All Fuel, MFT Acted, Turbine Tripped, Generator Class-A.							
5A) Observations: On Dt. 03/03/2018 at 12:30 hrs. set was on load 160 MW load with five C/c in service (B-s/by).							
Load was reduced by withdrawing C/c one by one, set tripped on 'Flame Failure'.  5B) Remedial Action/work done: No work carried out.							
<b>6. Root Cause Analysis:</b> As per directives of ED(O&M) KPKD U-3 is to be withdrawn as KRD U-9 is synchronized							
so as to maintain total DC.							
7. Preventive action suggested (Short Term):							
8. Preventive action suggested (Long Term):							
9. Similar event occurred last time:			U - 3, 210 MW Time:			Date:	
		*					
Event: No similar event found. Remedial Actions:							
9A. Implementation Status of Long Term/Short Term measures stated at Sr. No 7 & 8:-							
10. Boiler lighted up			Time - 00:10 Hrs			<b>Date -</b> 07/03/18	
11. T-A Set Synchronized			<b>Time</b> – 10:15 Hrs			<b>Date -</b> 07/03/18	
12. Remark: -							
Chief Engineer							
13. Recommendations of Works Section:							
1. Procurement/Replacement Plan:							
2. Operational Error:							
3. Delay in Maintenance:							
4. Delay in bringing back the Unit:							
5. Training of Staff:							
6. Whether remedial action is completed satisfactory & point is closed:							

C E/Dy C E (Works)