		EVE	NT ANALYSIS REPORT			
UNIT NO: 04			Un	it Capa	acity : 210 MW	
1. *HO Code :	Station Code : T003	Time 08:55			o. of days fro 3 days	m last sync. :
2. Operating c	onditions at the t	ime of E			J	
Load		Coal Cycles in service			Oil Support	
93 MW			A,B,C	NIL '		
3. Nature of Ev	ent: TA Set withdra	wn to atte	end Boiler Tube Leakage	at Eco	nomiser Zone	
	•		rotection on which GC			
Hand Tripped	(First Up), MFT Op	erated, Tu	irbine Tripped, Reverse	Power	Protection.	
			d "Boiler Tube Leakage			
			niser Coil no. 120 & 121	dumm	ied by welding	g hemispherical
	nomiser inlet & inte					
			as erosion might be the			
		120. Seco	ndary failure observed a	at Tube	e no. 2 coil no.	120 and Tube no. 2
of coil no. 12						
	ction suggested (S					
	ction suggested (L	0	,			
			nomiser coil no. 120 & 1			2
2. Replacen	nent of eroded Econ	iomiser co	ils as per Erosion profile	mapp	ing during for	thcoming AOH.
9. Similar event occurred last time:-			Unit No # 4, 210			Date:
7. Sillillai eveli	t occurred last tim	ie:-	MW	Time	e: 17:40 Hrs	08/12/2015
	forced withdrawn d		MW	Time	e: 17:40 Hrs	
Event: T.A. Set	forced withdrawn d	ue to Boile	MW er tube leakage.			08/12/2015
Event: T.A. Set	forced withdrawn d	ue to Boile	MW			08/12/2015
Event: T.A. Set : Remedial Action Economiser inle	forced withdrawn d ons: - Economiser t & intermediate he	ue to Boile upper ba	MW er tube leakage.	ed by	welding hemi	08/12/2015
Event: T.A. Set : Remedial Action Economiser inle	forced withdrawn dons: - Economiser t & intermediate heation Status of Lon	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg	ed by	welding hemi	08/12/2015 ispherical spool at
Event: T.A. Set: Remedial Action Economiser inle 9A. Implement	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugge Short Term measures s	ed by	welding hemi	08/12/2015 ispherical spool at :- 1/2016
Event: T.A. Set : Remedial Action Economiser inle 9A. Implement: 10. Boiler light	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding hemi at Sr No 7 & 8 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016
Event: T.A. Set and Remedial Action Economiser inlems 9A. Implement 10. Boiler light 11. T-A Set Syn	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding hemi at Sr No 7 & 8 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016
Event: T.A. Set and Remedial Action Economiser inlems 9A. Implement 10. Boiler light 11. T-A Set Syn	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding heminated Sr No 7 & 8 Date- 27/01 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016 1/2016
Event: T.A. Set : Remedial Action Economiser inle 9A. Implement: 10. Boiler light 11. T-A Set Syn 12. Remark:-	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding hemi at Sr No 7 & 8 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016 1/2016
Event: T.A. Set and Remedial Action Economiser inless 9A. Implementa 10. Boiler light 11. T-A Set Syn 12. Remark:-	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up archronized	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding heminated Sr No 7 & 8 Date- 27/01 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016 1/2016
Event: T.A. Set and Remedial Action Economiser inless 9A. Implementa 10. Boiler light 11. T-A Set Syn 12. Remark:-	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up achronized	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding heminated Sr No 7 & 8 Date- 27/01 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016 1/2016
Event: T.A. Set and Remedial Action Economiser inless 9A. Implementa 10. Boiler light 11. T-A Set Syn 12. Remark:-	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up achronized	ue to Boild upper ba ader. g Term/S	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding heminated Sr No 7 & 8 Date- 27/01 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016 1/2016
Event: T.A. Set : Remedial Action Economiser inle 9A. Implement: 10. Boiler light 11. T-A Set Syn 12. Remark:- 13. Recomment: 2. Operation 3. Delay in	forced withdrawn dons: - Economiser t & intermediate he ation Status of Lonted up achronized dations of Works Sment/Replacement and Error:	ue to Boile upper ba ader. g Term/S Section: t Plan:	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding heminated Sr No 7 & 8 Date- 27/01 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016 1/2016
Event: T.A. Set : Remedial Action Economiser inle 9A. Implement: 10. Boiler light 11. T-A Set Syn 12. Remark:- 13. Recomment: 2. Operation 3. Delay in	forced withdrawn dons: - Economiser the lintermediate here ation Status of Londerd up ted up ted up ted dations of Works Sment/Replacement and Error: Maintenance: bringing back the	ue to Boile upper ba ader. g Term/S Section: t Plan:	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding heminated Sr No 7 & 8 Date- 27/01 Date- 27/01	08/12/2015 ispherical spool at :- 1/2016 1/2016
Event: T.A. Set and Remedial Action Economiser inless 9A. Implements 10. Boiler light 11. T-A Set Syn 12. Remark:- 13. Recomments 1. Procurer 2. Operation 3. Delay in 4. Delay in 5. Training	forced withdrawn dons: - Economiser at & intermediate he ation Status of Long ted up achronized dations of Works Sment/Replacement and Error: Maintenance: bringing back the bof Staff:	ue to Boild upper baader. Ig Term/S Section: t Plan:	MW er tube leakage. ank coil no. 123 plugg Short Term measures s Time - 06:22 Hrs	ed by	welding heminated Sr No 7 & 8 Date- 27/01 Date- 27/01 Chief En	08/12/2015 ispherical spool at :- 1/2016 1/2016