		EVEN'	T ANALYSI	S REP	ORT		
UNIT NO: 02		Unit Capacity : 210 MW					
1. *HO Code :	Station Code :		ime –	ne - Date -		No. of days from last sync. :	
	Т003	03:	03:18 Hrs		/04/2015	41 days	
2. Operating c	onditions at the t	ime of E	vent :-				
Load			Coal Cycles in service			Oil Support	
65 MW			A,F				Nil
3. Nature of Ev	rent: T.A. Set with	lrawn for	Annual Ove	erhaul	2		
4. Name of Fir	st Up , Main Protec	tions & P	rotection	on wh	ich GCB trip	ped:	
Gen Protection	Operated,Turbine tr	rip, Gen. R	ev Power o	perat	ed, AVR PT F	use fail, P	Protection PT Fuse
fail.							
5A) Observati	ons: - Due to Critic	al Coal St	ock Positio	n, Set	was withdra	wn. Durir	ng withdrawal process
-	on Flame Failure at 1						
	Action/Work done			ed to A	Annual Overh	aul Carrie	ed out and separate
	ioning major works						
6. Root Cause					*		
7. Preventive	action suggested (S	Short Ter	m):-				÷
	action suggested (I						
Unit No # 2 ,						Date: 04 /07 /2045	
9. Similar event occurred last time:-		ne:-	210M	Time: 05:4		45 Hrs Date: 01/06/201	
Event: - Capit	cal Overhaul of set ca	rried out					
	t ions : All works pe			ied ou	t.		
	ntation Status of Lo					ed at Sr. N	0 7 & 8 :-
10. Boiler lighted up			Time - 01:40 Hrs			Date- 24/04/2015	
11. T-A Set Synchronized			Time - 16:45 Hrs			Date- 24/04/2015	
12. Remark :		-					
				2			
	Chief Engineer						
	CYAY	C				Giller	mgmeer
	endations of Works						
	ent/Replacement P	lan:					
2. Operationa							
3. Delay in Ma							
4. Delay in br	inging back the Un	it:					
5. Training of				13,000			
6. Whether re	emedial action is co	ompleted	satisfacto	ry & p	point is close		
						C E/Dy	CE (Works)