		E	VENT ANALYSIS RE	EPORT		 	
UNIT NO: 03	TPS: Khape	rkheda	TPS	-	U	nit Capacity: 210 MW	
4 *110 C .	Station Code		Time –	Date -	No	of Days from last sync. :	
1. *HO Code :	Station Code :	1003	00:00 Hrs	12/09/201	.7 5 d	5 days	
2. Operating co	nditions at the	time of	Event :-				
Load		Coal Cycles in service				Oil Support	
79 MW		C & D			Nil		
3. Nature of Eve	nt: T.A. Set with	drawn du	ue to Poor Coal Rece	eipt extended	d due to A	OH.	
	Up , Main Protectives Up), MFT, Ge		Protection on wha, Turbine Tripped.	nich GCB tri	pped:		
					load with	five C/c in service. Load was	
			et tripped on flame f		nner hank	& lower bank. AOH	
activities carried		Comple	te Replacement of E	conomizer u	ррег ратк	A R IOWEL DATK, AOF	
6. Root Cause Ar	nalysis: Due to "C	ritical Co	al Stock" set withdr	awn on 'Flam	ne Failure'	protection.	
7. Preventive act	tion suggested (S	Short Te	erm):				
8. Preventive act	tion suggested (I	ong Te	rm):		,		
9. Similar event occurred last time:			U - 3, 210 MW Time: 10:39 Hi		9 Hrs	Date : 20/07/2014	
Remedial Action	s: No Work done.		utage extended due			No 7 & 8 :-	
10. Boiler lighted up			Time - 22:03 Hrs			Date - 21/02/18	
11. T-A Set Synchronized			Time – 10:56 Hrs			Date - 21/02/18	
12. Remark: -			1000100			21/02/10	
Chief Engineer							
13. Recommenda	ations of Works S	Section:			*		
1. Procurement/	Replacement Pla	n:					
2. Operational En	ror:					· · · · · · · · · · · · · · · · · · ·	
3. Delay in Maint	enance:						
4. Delay in bring	ing back the Unit	:					
5. Training of Sta	aff:						
6. Whether reme	dial action is con	npleted	satisfactory & po	int is closed	d:		
C E/Dy C E (Worl	ks)						
1							