

Flash airline Flight 604

Flight model: Boeing 737
Date: January 3, 2004

From: Egypt
To: Paris, France

The captain in the flight was a former Egypt air force pilot who had been a part in many of the war that was fought by Egypt. The captain was considered as a model pilot. The airline Fash air, was found to have many safety problems in its plane when all its fleet was still operating.

Problem

Shortly after take off, Instead of turning left; the plane starts to turn right. When the pilot tries to stabilize the plane the situation turns worse. Then the auto pilot is turned on but, hardly make any change. When the plane falls down towards the ground, despite the best efforts of the pilot the ground proximity warning pops up. Then crashes into the red sea.

Investigation

The body of the jet, is found under the deep sea; with the help of the flight data recorder and DVR; they first try to find out why the plane turned right instead of turning left initially.

Scenario-1 The **spoilers** of the plane, which are located at the wings which help the plane turn left or right. If the cables connected to the spoilers were jammed. This would mean the spoilers in one same position forcing the plane to bank on one side.

Scenario-2 The **ailerons** which is located in the wings of a plane which help in controlling the angle of the plane. A malfunctioning aileron could have rolled the plane towards the right.

Scenario-3 The pilots shortly after take off turn on the auto pilot and then turn off the auto pilot after a few seconds. There is a probability that the auto pilot had not been disengaged and started to malfunction.

Scenario-4 The pilots should have suffered from **Vertigo**, a situation where in the pilot losses balance and become disoriented because of the pitch dark environment.

The flash airline have not provided crew resource management training for the pilot even through it mandatory to provide one which would have helped to manage the problem better.

Changes that were brought after the incident

It was recommended to include human resource training for the pilots for the airline. It also recommended training on what the other pilot should do when the pilot in command is disoriented.

Reference

1. Flight 604's Mysterious Crash Over the Red Sea — Mayday: Air Disaster
<https://www.youtube.com/watch?v=5zgB4v3MHKg>