





Member of the Phoenix Contact Group

S T Series

Shielded Connectors M17/Speedcon

Shielded Connectors M17/Speedcon Series ST Technical Data



Shell material

Machined components: Copper-Zinc alloy (CuZn)

die cast components: Zinc (GD-Zn)
Shell plating: Nickel (Ni) plated
Cable entry: max. 12.5 mm



Insulator

Connector inserts: Polyamid (PA66),

Contacts

Contact material: Copper-Zinc alloy (CuZn)

Contact plating: Nickel (Ni) with gold (Au) passivated

Contact termination: crimp type




Sealing

Sealing rings: Fluor rubber (FPM)
Gaskets: Fluor rubber (FPM)

Temperature

Temperature (long term) Celsius: $-20 \, ^{\circ}\text{C}$ up to $+125 \, ^{\circ}\text{C}$ Temperature (long term) Fahrenheit: $-4 \, ^{\circ}\text{F}$ up to $+257 \, ^{\circ}\text{F}$



All connectors with universal

Mating

Female coupling nuts: M17, or M17 in Speedcon Male receptacles: M17, or M17 in Speedcon

Mating cycles: Standard min. 50



EMC shielding

Protection

Protection class: IP 67 (mated) depends on which cable gland is used

		0000		0000		0	
Number of positions	4	6	7	8	8	12	17
Number of contacts	3 + PE	5 + PE	6 + PE	7 + PE	8	12	17
Contact dia. (mm Ø)	2	1	1	1	1	0.6	0.6
Rated current at 25°C (A)	20/25	14	14	14	3.6	3.6	3.6
Rated voltage (V)	630	630	630	630	60	60	60
Test voltage (Volt AC)	4,000	6,000	6,000	6,000	1,500	1,500	1,500
Overvoltage category DIN EN 61984-2001							
Installation altitude above sea level	3,000 m						



Shielded Connectors M17/Speedcon Series ST Shell styles 8, 8S, 9S, WQ, W4, AD

ST-xxxxxxx8xxx	ST-xxxxxxx8xxxS	ST-xxxxxxx9xxxS
page C-D-04	page C-D-04	page C-D-05
cable connector straight	cable connector straight	cable connector straight
with coupling nut M17	with coupling nut M17 (1/2 turn)	with outside thread M17 (1/2 turn)
cable entry max. 12.5 mm	cable entry max. 12.5 mm	cable entry max. 12.5 mm
universal shielding material	universal shielding material	universal shielding material
style 80 ST-xxxxxxxWQxxS	style 80 ST-xxxxxxxW4xxS	style 90 ST-xxxxxxxADxxS
page C-D-06	page C-D-06	page C-D-07
front mount, straight	front mount, straight, snap in	front mount, angled rotary
square flange, axial O-ring	square flange, axial O-ring	square flange, axial O-ring
flange with holes	flange with holes	flange 21.6 x 21.6 with holes
with outside thread M17 (1/2 turn)	with outside thread M17 (1/2 turn)	with outside thread M17 (1/2 turn)
style WQ	style W4	style AD



Shielded Connectors M17/Speedcon Series ST Shell style AC, 61, H1, 8K, 9K, CK

ST-xxxxxxxACxxS	ST-xxxxxxx61xxS	ST-xxxxxxxH1xxS
page C-D-07	page C-D-08	page C-D-09
front mount, angled rotary	front mount, straight	rear mount, straight
square flange, axial O-ring	round flange, axial O-ring	round flange, axial O-ring
flange 25 x 25 with holes	mounting thread M18x0.75 mm	mounting thread M20x1.5 mm
with outside thread M17 (1/2 turn)	with outside thread M17 (1/2 turn)	with outside thread M17 (1/2 turn)
	M17 SPEEDCON	
style AC ST-xxxxxxx8KxxS	style 61 ST-xxxxxxx9KxxS	style H1 ST-xxxxxxxCKxxS
page C-D-10	page C-D-11	page C-D-12
cable connector straight	cable connector straight	cable connector with flange
with coupling nut M17 (1/2 turn)	with outside thread M17 (1/2 turn)	with outside thread M17 (1/2 turn)
cable entry max. 12.5 mm	cable entry max. 12.5 mm	cable entry max. 12.5 mm
universal shielding material	universal shielding material	universal shielding material
1/2	1/2	1/2
style 8K	style 9K	style CK




Shielded Connectors M17/Speedcon Series ST Shell style WK, W5, A4, A5

ST-xxxxxxxWKxxS	ST-xxxxxxxW5xxS	ST-xxxxxxxA4xxS
page C-D-13	page C-D-14	page C-D-15
front mount, straight	front mount, straight	front mount, angled
square flange, axial O-ring flange 25.75 x 25.75 with holes	square flange, axial O-ring flange 25.75 x 25.75 with holes	square flange, axial O-ring flange with holes M2.5
with outside thread M17 (1/2 turn)	with outside thread M17 (1/2 turn)	with outside thread M17 (1/2 turn)
style WK	style W5	style A4
ST-xxxxxxxA5xxS page C-D-16		
front mount, angled square flange, axial O-ring flange with holes M3 with outside thread M17 (1/2 turn)		
12		
style A5		




fits all ST- Bulkhead

Shell style 80xx/80xxS





fits all ST- Bulkhead Shell style 90xxS



Crimp tool for contacts: pages B-B-00...

Crimp contacts: pages B-C-20.....


Connector with crimp insert - and

contacts separate included. Please ask for P/N.

Part Number	ST-	Х	Х	Х	1	Ν	8	Α	9	0	0	Х	S
Please fill in the first 7 digits	s of	_											
your desired connector inse	ert (4-17	positi	ions)										
from pages B-A-50													
Connectors with integra	ated str	ain ı	relief	and									
seal ring for 3.5 - 4 mm Ø									9	0	0	1	
-													
seal ring for 4 - 5 mm Ø									9	0	0	2	
ocurring for 4 o min go									9	•		_	
seal ring for 5 - 8 mm Ø									9	0	0	3	
seal ring for 8 - 10 mm Ø									9	0	0	4	
seal ring for 10 - 12.5 mm Ø									9	0	0	5	
Joan 11119 101 10 - 12.0 111111 Ø									J	U	U	J	




fits all ST-Cable Connectors with coupling nut
Shell style WQ/W4 (front mount receptacles)






fits all ST-Cable Connectors with coupling nut
Shell style AD/AC (front mount receptacles)






fits all ST-Cable Connectors with coupling nut
Shell style 61 (front mount receptacles)






fits all ST-Cable Connectors with coupling nut
Shell style H1 (rear mount receptacles)





fits all ST- Bulkhead Shell style 8KxxS







Assembly instructions: page B-D-38
Caps and accessories: pages: B-H-01...

Mounting tools: N/A

Crimp tool for contacts: pages B-B-00...

Crimp contacts: pages B-C-20.....

All ST-connectors with universal shielding material for different jacket and shield diameters.

ket and shield diameters.

We also deliver as a connector set.

Connector with crimp insert - and

contacts separate included. Please ask for P/N.

Please fill in the first 7 digits of your desired connector insert (4-17 positions) from pages B-A-50....

Connectors with integrated strain relief and....


8 K 0 2 S

seal ring for $3.5 - 5.5 \, \text{mm} \, \emptyset$ 8KO2Sseal ring for $5 - 9 \, \text{mm} \, \emptyset$ 8KO3Sseal ring for $9 - 11 \, \text{mm} \, \emptyset$ 8KO4S



fits all ST- Bulkheads or Cables

Shell style 9KxxS








Assembly instructions: page B-D-38 Caps and accessories: pages: B-H-01...

Mounting tools: N/A

Crimp tool for contacts: pages B-B-00... Crimp contacts: pages B-C-20.....

All ST-connectors with universal shielding material for different jacket and shield diameters.




We also deliver as a connector set. Connector with crimp insert - and


contacts separate included. Please ask for P/N.

Part Number	ST-	Х	X	Х	1	N	8	Α	9	K	0	X	X
Please fill in the first 7 digits of your desired connector insert (4-17 positions) from pages B-A-50													
Connectors with integr	ated str	ain ı	elief	and									
seal ring for 3.5 - 5.5 mm \emptyset seal ring for 5 - 9 mm \emptyset seal ring for 9 - 11 mm \emptyset										K K K			




Shell style CKxxS (front mount and rear mount)





N





Assembly instructions: page B-D-38
Caps and accessories: pages: B-H-01...

Mounting tools: N/A

Crimp tool for contacts: pages B-B-00...

Crimp contacts: pages B-C-20....

All ST-connectors with universal shielding material for different jacket and shield diameters.

We also deliver as a connector set.

Connector with crimp insert - and

contacts separate included. Please ask for P/N.

 $\mathbf{x} \mid \mathbf{x}$

Please fill in the first 7 digits of

Please fill in the first 7 digits of your desired connector insert (4-17 positions) from pages B-A-50....

Connectors with integrated strain relief and....


seal ring for 3.5 - 5.5 mm \emptyset seal ring for 5 - 9 mm \emptyset seal ring for 9 - 11 mm \emptyset



C K 0 2 S C K 0 3 S C K 0 4 S



Shell style WKxxS



Assembly instructions: page B-D-41 Caps and accessories: pages: B-H-01...

Mounting tools: N/A

Crimp tool for contacts: pages B-B-00...
Crimp contacts: pages B-C-20....

We also deliver as a connector set.

Connector with crimp insert - and

contacts separate included. Please ask for P/N.

Part Number ST- x x x x 1 N 8 A W K 0 0 S

Please fill in the first 7 digits of

your desired connector insert (4-17 positions)

from pages B-A-50....

Connectors with integrated strain relief and....

the insert should be snapped in before mounting

square flange connector, 25.75 x 25.75

front mount, with axial O-ring

with outside thread M 17/Speedcon










Shell style W5xxS



Assembly instructions: page B-D-41 Caps and accessories: pages: B-H-01...

Mounting tools: N/A

Crimp tool for contacts: pages B-B-00...

Crimp contacts: pages B-C-20....

We also deliver as a connector set.

Connector with crimp insert - and

contacts separate included. Please ask for P/N.

Part Number ST- x x x x 1 N 8 A W 5 0 0 S

Please fill in the first 7 digits of

your desired connector insert (4-17 positions)

from pages B-A-50....

Connectors with integrated strain relief and....

the insert is fixed with the installation of the connector

square flange connector, 25.75 x 25.75

front mount, with axial O-ring

with outside thread M 17/Speedcon












Shell style A4xxS







Assembly instructions: page B-D-39
Caps and accessories: pages: B-H-01...

Mounting tools: N/A

Crimp tool for contacts: pages B-B-00...

Crimp contacts: pages B-C-20.....

We also deliver as a connector set.


Connector with crimp insert - and


contacts separate included. Please ask for P/N.


Please fill in the first 7 digits of your desired connector insert (4-17 positions) from pages B-A-50.... Connectors with integrated strain relief and.... 4 holes with 2.7 mm square flange connector, 25.75 x 25.75 front mount, with axial O-ring with outside thread M 17/Speedcon



Shell style A5xxS







Assembly instructions: page B-D-39
Caps and accessories: pages: B-H-01...

Mounting tools: N/A

Crimp tool for contacts: pages B-B-00...

Crimp contacts: pages B-C-20.....

We also deliver as a connector set.

Connector with crimp insert - and

contacts separate included. Please ask for P/N.

Please fill in the first 7 digits of your desired connector insert (4-17 positions) from pages B-A-50.... Connectors with integrated strain relief and.... 4 holes with 3.2 mm square flange connector, 25.75 x 25.75 front mount, with axial 0-ring with outside thread M 17/Speedcon