ORIGINAL FOR RECIPIENT / DUPLICATE FOR TRANSPORTER // TRIPLICATE FOR SUPPLIER



## J.J. IMPEX (DELHI) PRIVATE LIMITED

MARUTI SERVICE MASTERS

C-7, SMA Industrial Estate, G. T. Karnal Road, Metro Pillar No.-136, Opp. Jahangirpuri, Delhi- 110033 Ph.: 40715500/01, 27693870/71/72, Fax: 2769 3256

Regd. Office: F-39, Okhla Indl. Area Phase-II (Near C.Lal Chowk), New Delhi-20 ORIGINAL FOR RECIPIENT/DUBLICATE FOR WELSHER, WWW.MARUHORSO.COP. LER



## Job Card Retail - Tax Invoice

Customer Name & Address :

ID: 1725279461

Fuel Trim:

Invoice No.: 002/BR/18018865

Date: 06/02/2019 18:11:05

**OLA FLEET TECHNOLOGIES PVT LTD** 

PLOT NO-86 UDYOG VIHAR PH-1

GURGAON

State & Code: 06-HARYANA

Mobile Loyalty Card : NA

9953796004

Cust GSTIN/UIN: 06AAKCA2311H1Z4

Job Card No. : JC18020002

Reg.No. ; HR55AB5687 SA Name: VERINDER SINGH

Model: MARUTI WAGON R LXI

Chassis No.; C70911

Service type: RUNNING REPAIR

EW Type: NA

Job Card Date: 25/01/2019 Mileage: 119086

SA(M):9711474941 Last Service : 111010 (17-12-18) Next Service Due: PMS120

Place of Supply: HARYANA

Srl.	Part Number	Description Ba	atch HSN/SAC Tax Qty.	Rate	Taxable Amount	Tax Paid Amount	Labour Charges
Lab	our						
Dem	anded Repairs-Others	/Suggested Jobs					
2	HJ04R01	REAR SHOCK ABSORBER (ONE SIDE) WITH OPPOSITE SIDE	998729				406.0
	QJ02R0	REAR VIEW MIRROR ASSY (ONE SIDE)	998729				174.0
Ä	AJ13R0	ENGINE MOUNTING (RH)	998729				348.0
	HA02R01	FRONT STRUT (ONE SIDE) WITH OPPOSITE SIDE	998729				928.0





Recommendations:

Dealer GSTIN: 07AAACJ1841P2ZC

Net Bill Amount (Rounded)	22,382.0			
Sub Total Amount	:	18,316.28	0.00	4,065.34
IGST @ 18%		388.72		620.14
IGST @ 28%	:	3,449.24		
Less Discount		762.02	0.00	382.80
Sub Total Amount		15,240.34	0.00	3,828.00

**Authorised Signatory** 

Rupees Twenty Two Thousand Three Hundred And Eighty Two Only

\* Unapproved fitments may affect your and vehicle safety. Kindly do not fit any unapproved fitments in your vehicle.

l acknowledge that the jobs/repairs/service carried out in my vehicle and the respective cost estimates were explained to me. I have received my vehicle after completion of all repairs being carried out to my satisfaction and I confirm that my vehicle is in good condition. I further authorize this workshop to contact me by call or sms to inform me with any other information in relation to my vehicle.

**Customer Signature** 

Mobile No .:

ORIGINAL FOR RECIPIENT / DUPLICATE FOR TRANSPORTER // TRIPLICATE FOR SUPPLIER



## J.J. IMPEX (DELHI) PRIVATE LIMITED

MARUTI SERVICE MASTERS

C-7, SMA Industrial Estate, G. T. Karnal Road,
Metro Pillar No.-136, Opp. Jahangirpuri, Delhi- 110033
Ph.: 40715500/01, 27693870/71/72, Fax: 2769 3256

Regd. Office: F-39, Okhla Indl. Area Phase-II (Near C.Lal Chowk), New Delhi-20

ORIGINAL F-Mail: CUSTOMERCASE ET & MARY TO MEDINE: WWW.MARE TIMES MARY TO MEDINE.



## Job Card Retail - Tax Invoice

Customer Name & Address:

ID: 1725279461

Invoice No.: 002/BR/18018865

Date: 06/02/2019 18:11:05

OLA FLEET TECHNOLOGIES PVT LTD PLOT NO-86 UDYOG VIHAR PH-1

GURGAON

Job Card No. : JC18020002 Reg.No. : HR55AB5687

Job Card Date: 25/01/2019 Mileage: 119086

State & Code: 06-HARYANA 9953796004 Mobile : 9953 Loyalty Card : NA

SA Name: VERINDER SINGH Model: MARUTI WAGON R LXI SA(M):9711474941

Fuel Trim: Chassis No.: C70911 EW Type: NA Last Service: 111010 (17-12-18) Next Service Due: PMS120

Cust GSTIN/UIN: 06AAKCA2311H1Z4

Service type: RUNNING REPAIR Place of Supply: HARYANA

Srl.	Part Number	Description	Batch	HSN/SAC	Tax	Qty.	Rate	Taxable Amount	Tax Paid Amount	Labour Charges
art	ts									
Dem	anded Repairs-Others	s/Suggested Jobs								
1	01550M1060A	BOLT	AA	7318	28%	1.000	9.37	9.37	0.00	
2	09159M12042	NUT,WHEEL	AA	7318	18%	5.000	8.89	44.45	0.00	
	11610M67L00	MOUNTING, ENG RH	AA	8708	28%	1.000	605.46	605.46	0.00	
4	11620M67L00	MOUNTING, ENG LH	AA'	8708	28%	1.000	601.56	601.56	0.00	
	11710M67L00	MOUNTING, ENG RR	AA	8708	28%	1.000	548.43	548.43	0.00	
	12620M68K10	FLYWHEEL COMP	AA	8483	18%	1.000	1449.15	1449.15	0.00	
7	12623M68K00	BEARING, INPUT SHAFT	AA	8482	18%	1.000	103.38	103.38	0.00	
	22100M67KC0	COVER ASSY, CLUTCH	AA	8708	28%	1.000	664.06	664.06	0.00	
9	22400M67KC1	CLUTCH DISC NEW WAGON-R 2010	AA	8708	28%	1.000	847.65	847.65	0.00	
10	23265M79F00	BEARING, CLUTCH RELEASE	AA	8708	28%	1.000	453.12	453.12	0.00	
11	23710M67L01	CABLE ASSY, CLUTCH RH	AA	8708	28%	1.000	213.28	213.28	0.00	
12	27431M74L00	SEAL, DIFFERENTIAL SIDE RH	AA	4016	18%	1.000	138.13	138.13	0.00	
13	27432M74L00	SEAL, DIFFERENTIAL SIDE LH	AA	4016	18%	1.000	105.08	105.08	0.00	
14	41601M67L01	STRUT ASSY, FR SUSPENSION RH	AA	8708	28%	1.000	925.78	925.78	0.00	
15	41602M67L01	STRUT ASSY, FR SUSPENSION LH	AA	8708	28%	1.000	925.78	925.78	0.00	
16	41710M67L01	SUPPORT, FRONT STRUT	AA	8708	28%	2.000	300.00	600.00	0.00	
17	41800M67L32	ABSORBER ASSY, REAR SHOCK	AA	8708	28%	2.000	871.09	1742.18	0.00	
	44101M67LA2	SHAFT ASSY, FRONT DRIVE, R	AA	8708	28%	1.000	4011.71	4011.71	0.00	
19	55210M79F00	PAD FR DISC BRAKE(1 PCS)	AA	8708	28%	4.000	204.68	818.72	0.00	
20.	84701M67L02	MIRROR ASSY, OUT REAR VIEW, R	AA	7009	18%	1.000	433.05	433.05	0.00	
ab	our	GERTIFIED					5/4s #	100 /	A Phillip	
Dema	anded Repairs-Others	s/Suggested Jobs					EX IDE	3 6 6 a 1		
1	ZE20L0	CLUTCH BLEEDING		998729			LOEN HOE	177/	AN HE AND IDEASON.	1,972.0
							100	10.		

INDUSTRIAL

ROAD, DEL