

J.J. IMPEX (DELHI) PRIVATE LIMITED MARÙTI SERVICE MASTERS C-7, SMA Industrial Estate, G. T. Karnal Road,

Metro Pillar No.-136, Opp. Jahangirpuri, Delhi- 110033 Ph.: 40715500/01, 27693870/71/72, Fax: 2769 3256 Regd. Office: F-39, Okhla Indl. Area Phase-II (Near C.Lal Chowk), New Delhi-20 ORIGINAL FOR RECIPIENT/DUPLICATE FOR TRANSPORTER WREDE CATE FOR TRANSPORTER TR

Job Card Retail - Tax Invoice

Customer Name & Address

ID: 1726100907

Fuel Trim:

Invoice No.: 002/BR/18016560

Date: 30/12/2018 18:35:48

OLA FLEET TECHNOLOGIES PVT LTD

Plot No. 230, 1st Floor, Udyog Vihar, Phase-I

GURGAON

State & Code: 06-HARYANA 8506868026

Mobile : 850 Loyalty Card : NA

Cust GSTIN/UIN: 06AAKCA2311H1Z4

Job Card No. : JC18018014

Reg.No. : HR55AB4110 SA Name : VERINDER SINGH

Model: MARUTI SWIFT DZIRE LXI EW Type: NA
Last Service: 72954 (28-06-18)

Chassis No.: A99723 Service type: RUNNING REPAIR Job Card Date: 27/12/2018 Mileage: 94275

SA(M):9711474941

Next Service Due: PMS 20

				Service type: RUNNING REPAIR Place of Supply: HARYANA					SEZ Customer		
Srl.	Part Number	Description	Batch	HSN/SAC	Tax	Qty.		Rate	Taxable Amount	Tax Paid Amount	Labour Charges
Part	S										
Dema	anded Repairs-Others/	Suggested Jobs									
1	09409M07L01	CLIP	AA	3926	28%	10.000		2.34	23.40	0.00	
2	09409M08L01	CLIP	AA	8708	28%	5.000		2.34	11.70	0.00	
3	09471M12057	BULB,21/5 W,12V	AA	8539	18%	1.000		43.22	43.22	0.00	
4	09471M12076	BULB	AA	8512	18%	4.000		29.66	118.64	0.00	
5	09471M12090	BULB 12V(SX4 MINOR 2009)	AA	8539	28%	2.000		71.09	142.18	0.00	
6	11610M74LA0	MOUNTING, ENG RH	AA	8708	28%	1.000		2183.59	2183.59	0.00	
7	36410M67K00	LAMP ASSY, SIDE TURN	AA	8512	. 18%	1.000		97.45	97.45	0.00	
8	37210M74L00	SWITCH ASSY, LIGHTING & TURI	N AB	8537	18%	1:000		377.96	377.96	0.00	
9	38480M74L00	NOZZLE, WASHER	AA	8708	28%	2.000		32.81	65.62	0.00	
	72322M74L00	LINING, FRONT FENDER LH	AA	8708	28%	1.000		265.62	265.62	0.00	
Labo	our										
Dema	inded Repairs-Others/	Suggested Jobs				-	TIDI	-7			
	ZA64L0	OUT SIDE LABOUR		998729		108	KILL	LHD			500.00
	SD42R01	Rear Combination Lamp Socket & (Cord	998729		137		(P)	1		232.00
		Assy (One Side) WITH OPPOSITE			1	4/		12	1		
3	AJ13R0	ENGINE MOUNTING (RH)		998729	1-	5/ 0	2-7 5	SAMA IT	1		348.00
4	NH02R0	FRONT FENDER EMBLEM (ONE	SIDE)	998729	17		1107	PIVIA I	31		116.00
		ISO 9001			6.1.	E	STA	TEA	XEDE		G
		VINCOTTE				AL P.	040,	DELY	CAR	CARE	oriones d'
Pace	ommendations :		Sub Total A	Amount					3,329.38	0.00	1,196.00
			Less Discou						166.47	0.00	119.6
		TARGED FOR PETROL	IGST @ 289						716.10		
FILL	UP		IGST @ 18°					:	108.97		193.7
			Sub Total A	mount		,			3,987.98	0.00	1,270.15
			Net Bill A	Amount (Ro	unded	1)	:				5,258.00
		Authorised Signatory		_							
		Authorised orginatory	Rupees	Five Thousan	a Iwo h	rundred A	and hit	ty Eight Only	/		
	er GSTIN: 07AAAC									oved fitments in your	

I acknowledge that the jobs/repairs/service carried out in my vehicle and the respective cost estimates were explained to me, I have received my vehicle after completion of all repairs being carried out to my satisfaction and I confirm that my vehicle is in good condition. I further authorize this workshop to contact me by call or sms to inform me with any other information in relation to my vehicle.

Customer Signature

Mobile No.:

Gate Pass

·GP18017563 Tech. Name : ARJUN KUMAR

Date : 30-DEC-18 18:36:16

Cust. Name : M/S OLA FLEET TECHNOLOGIES | Model : SWIFT NEW / DZIRE NEW PETROL

Reg.No.; HR55AB4110

Job Card No. JC18017021 JC18018014

Bill.No. BR/18016330 BR/18016560 Bill Date 27-DEC-18 30-DEC-18

Amount 7,007.00 5.258.00

Customer Signature

Accountant Signature



IC18018014