
NDT MAP - GENERAL		Rev. 0	
CRUDE CHARGE HEATER 11-F-101			PERTAMINA
PT. PERTAMINA (PERSERO) REFINERY UNIT VI			
Check by:	Approved by:		



NDT MAP - GENERAL Rev. 0			
CRUDE CHARGE HEATER 11-F-101			PERTAMINA
PT. PERTAMINA (PERSERO) REFINERY UNIT VI			
Check by:	Approved by:		

