

List Bat

Update Bat

Instrument Setup: %R LAV SCI UV Cal
Date: 21-Jul-22 Time: 14:46:11

CMC DE Pass/Fail Tolerance: 1.00

I:c Ratio: (2.00 1.00)

New Bat Retrieve Bat Store Bat

Measured by:

* $\Phi \nabla$
**Pool Stronger

**pool Stronger

**pool Meaker

-0.5

0.0

-0.5

0.5

-\Delta b*

Delta D65 / 10 F11 / 10 A / 10

Single/All
CMC Plot
Zoom Out
Zoom In
Print Form

+∆L*

-∆L*

0.0

Batch Name	III/Obs	DL*	<u>Da*</u>	Db*	DL*/ISL	DC*/cSC	DH*/SH	CMC DE	<u>M.I.</u>	<u>P/F</u>	Color C	<u>comments</u>
	D65 10 Deg F11 10 Deg A 10 Deg		-0.33 0.30 -0.12	0.72 0.76 0.59	0.04 0.03 0.04	0.80 0.62 0.59	0.19 -0.66 0.30	0.83 0.91 0.66	0.63 0.25	Warn too light Warn too light Pass too light	too bright	too blue too yellow too green