

List Bat

Update Bat


Instrument Setup: %R LAV SCI UV Cal Date: 08-Sep-22 Time: 13:13:55

CMC DE Pass/Fail Tolerance: 1.00

I:c Ratio: (2.00 1.00)

New Bat Retrieve Bat Store Bat

Measured by:



Batch Name	III/Obs	DL*	<u>Da*</u>	Db*	DL*/ISL	DC*/cSC	DH*/SH	CMC DE	<u>M.I.</u>	<u>P/F</u>	Color C	<u>Comments</u>
HJY18402 B22147210AA-001 1-1K1 3042057/VII/22 BOLD	D65 10 Deg	0.22	-0.22	0.54	0.11	0.22	0.46	0.52		Pass too light	too bright	too yellow
HJY18402 B22147210AA-001 1-1K1 3042057/VII/22 BOLD	F11 10 Deg	0.30	-0.38	0.60	0.14	0.22	0.56	0.62	0.17	Pass too light	too bright	too yellow
HJY18402 B22147210AA-001 1-1K1 3042057/VII/22 BOLD	A 10 Deg	0.21	-0.44	0.56	0.10	0.15	0.73	0.75	0.22	Warn too light	too bright	too yellow