

List Bat

Update Bat


Instrument Setup: %R LAV SCI UV Cal Date: 22-Dec-22 Time: 14:14:27

CMC DE Pass/Fail Tolerance: 1.00

I:c Ratio: ( 2.00 1.00)

New Bat Retrieve Bat Store Bat

Measured by:



Single/All

CMC Plot

Zoom Out

Zoom In

Print Form

Batch Name	III/Obs	DL*	<u>Da*</u>	Db*	DL*/ISL	DC*/cSC	DH*/SH	CMC DE	<u>M.I.</u>	P/F	Color C	<u>Comments</u>
R22218265 LU00141-A10ACB 41767 3061222/X/22COLL PU	D65 10 Deg	-0.01	-1.00	1.01	-0.01	-0.65	-0.07	0.65		Pass too dark	too dull	too blue
R22218265 LU00141-A10ACB 41767 3061222/X/22COLL PU	F11 10 Deg	-0.01	-0.82	1.23	-0.00	-0.67	0.01	0.67	0.25	Pass too dark	too dull	too red
R22218265 LU00141-A10ACB 41767 3061222/X/22COLL PU	A 10 Deg	-0.03	-0.54	0.87	-0.02	-0.52	0.01	0.52	0.45	Pass too dark	too dull	too red