


Date: 29-Mar-21 Time: 12:00:44

Retrieve Bat Store Bat New Bat List Bat Instrument Setup: %R LAV SCI UV Cal Single/All

Batch Name

HBBA-21-01197 70005400 1-1 3013820/III/21 HBBA-21-01197 70005400 1-1 3013820/III/21



Zoom Out

Zoom In

CMC Plot

DataColor TOOLS 2.4.4 S/N NO.

Standard %R

400-450nm 29.05	32.12	32.08	28.50	23.56	18.91
460-510nm _{15.00}	11.87	9.21	7.52	6.15	5.09
520-570nm 4.54	4.17	3.89	3.85	4.04	4.41
580-630nm 4.81	5.51	8.30	14.75	26.17	38.96
640-690nm 49.69	57.66	64.42	69.24	72.63	73.86
700nm 76.37					

CMC DE Pass/Fail Tolerance: 0.80

I:c Ratio: (2.00 1.00)

III/Obs DL'	<u>* Da*</u>	Db*	DL*/ISL	DC*/cSC	DH*/SH	CMC DE	<u>M.I.</u>	<u>P/F</u>	Color Cor	<u>mments</u>
D65 10 Deg -0.3	37 -1.7	2 1.10	0 -0.21	-0.76	0.08	0.79		Warn darker	less saturated	more red
F11 10 Deg -0.8	38 -2.3	6 0.52	2 -0.50	-0.86	-0.58	1.15	1.13	Fail darker	less saturated	more blue

Print Form