

List Bat

Update Bat


Instrument Setup: %R LAV SCI UV Cal Date: 02-Nov-23 Time: 09:54:45

CMC DE Pass/Fail Tolerance: 1.00

I:c Ratio: (2.00 1.00)

New Bat Retrieve Bat Store Bat

Measured by:



Zoom In

<u>B</u>	Batch Name	III/Obs	DL*	<u>Da*</u>	Db*	DL*/ISL	DC*/cSC	DH*/SH	CMC DE	<u>M.I.</u>	P/F		Color C	<u>Comments</u>
		D65 10 Deg	0.39	-0.60	0.14	0.38	-0.23	-0.81	0.93		Warn	too light	too dull	too green
R1	117150 PR2324/613587 98635EXP2300839 BLACK	F11 10 Deg	0.36	-0.42	0.10	0.35	0.12	-0.56	0.67	0.19	Pass	too light	too bright	too green
R1	117150 PR2324/613587 98635EXP2300839 BLACK	A 10 Deg	0.33	-0.54	-0.02	0.32	-0.33	-0.64	0.79	0.18	Warn	too light	too dull	too blue