Visual Hue Request:

New Std Retrieve Std Store Std List Std Update Std

Instrument Setup: %R LAV SCI UV Cal
Date: 19-May-23 Time: 11:25:04

Batch Name 4 of 5

1020059IR-01 106911 EXP2300818 COMPASS K

List Bat

Update Bat


Instrument Setup: %R LAV SCI UV Cal Date: 23-Nov-23 Time: 14:09:24

CMC DE Pass/Fail Tolerance: 1.00

I:c Ratio: (2.00 1.00)

New Bat Retrieve Bat Store Bat

Measured by:



Batch Name	III/Obs	DL*	<u>Da*</u>	<u>Db*</u>	DL*/ISL	DC*/cSC	DH*/SH	CMC DE	<u>M.I.</u>	P/E	Color	Comments
DKF19106 24020059IR-01 106911 EXP2300818 COMPASS K DKF19106 24020059IR-01 106911 EXP2300818 COMPASS K DKF19106 24020059IR-01 106911 EXP2300818 COMPASS K	F11 10 Deg		0.38 0.49 0.36	-0.22 -0.27 -0.18	-0.59 -0.60 -0.57	-0.14 -0.17 -0.05	-0.48 -0.56 -0.52	0.77 0.84 0.77	0.10 0.09	Warn too dar Pass too dar Pass too dar	k too dull	too red too red too red