

List Bat

Update Bat


Instrument Setup: %R LAV SCI UV Cal Date: 21-Feb-24 Time: 09:37:22

CMC DE Pass/Fail Tolerance: 0.80

I:c Ratio: (2.00 1.00)

New Bat Retrieve Bat Store Bat

Measured by:



Batch Name	III/Obs	DL*	<u>Da*</u>	Db*	DL*/ISL	DC*/cSC	DH*/SH	CMC DE	<u>M.I.</u>	<u>P/F</u>	Color Co	<u>omments</u>
R1117150 B23179904AA-001 117416 EXP2300970 R1117150 B23179904AA-001 117416 EXP2300970	D65 10 Deg F11 10 Deg		0.04 0.02		-0.66 -0.69	0.10 0.04	0.29 0.10	0.73 0.70	0.17	Warn too dark Pass too dark	ŭ	too yellow too yellow