


Week 4 Tutorial

(Graphic technique is replaced with analytical method)

3-15 Figure P3-4 shows a non-Grashof fourbar linkage that is driven from link O_2A . All dimensions are in centimeters (cm).

- Find the transmission angle at the position shown.
- Find the toggle positions in terms of angle AO_2O_4 .
- Find the maximum and minimum transmission angles over its range of motion by graphical techniques.



*3-22 Find the maximum and minimum transmission angles of the fourbar driving stage (links L_1, L_2, L_3, L_4) in Figure P3-7 to graphical accuracy.





FIGURE P3-7

- *3-23 Figure P3-8 shows a fourbar linkage used in a power loom to drive a comblike reed against the thread, “beating it up” into the cloth. Determine its Grashof condition and its minimum and maximum transmission angles to graphical accuracy.



[View as a video](http://www.designof-machinery.com/DOM/loom_laybar_drive.avi)

http://www.designof-machinery.com/DOM/loom_laybar_drive.avi

FIGURE P3-8