

Detailed report

12/08/2026 - 18/08/2026

Total: 25:25:00



Date	Description	Duration	User
17/08/2026	Discussion, job writeups. Contemplating Workshop General	02:00:00 14:30:00 - 16:30:00	Aaron
17/08/2026	Temporary repair to chain where exchange table connects- will need proper servicing shortly. I believe an issue with the Top table sensor is causing the driving motor to place extra force on the chain. Around Beasley Ave	03:00:00 11:30:00 - 14:30:00	Aaron
17/08/2026	Time inclusive of driving. Took note of maintenance that will be required. Fitted test gripper cover- modifications to final cover next. Issues present with machine; Small ball rollers behind punches 1 to 3 need replacing. Since next to punch three and sensor inside Z axis punch likely need maintenance or replacing- same issues reoccurred. Roller closest to sharing blade needs to be adjusted forward Clamping arms are working with a lack of pressure. Inconsistencies of punch hole in centre of part – potentially the gripper feed being misaligned on bent rollers GGE - GGE ALFA500	03:00:00 08:30:00 - 11:30:00	Aaron
15/08/2026	Compressor maintenance; Lift compressor and place on wooden blocks. Reinstall auto drain valve in accessible location for ease of continued maintenance and installed hose for directing water to outside of compressor footprint. Replace air hose into compressor tank- took longer than expected due to glue and corrosion. Fix hose from compressor output to workshop- heavy corrosion on hose fitting will need replacing next maintenance cycle. Sean completed general maintenance + video documented procedure for use in future. Gweike 4020 GALL ; Clean and Inspect Bellows for damage – patches required on left side cross beam Bellows and Velcro/reattachment system needed for right Y axis bellows. Cleaned rack and bearing Bellows and tested for oiling. oil viscosity is too thick- need to find a thinner oil as it is not reaching Y axis bearings suitably. Checked water chiller water, cleanliness and was good so no replacement of water required. We noticed that the table exchange chain is highly damaged and will need maintenance ASAP- probably gonna break shortly. Also need to fix the intermittent issue with the computer- another maintenance visit will be required. Around Beasley Ave	09:00:00 07:30:00 - 16:30:00	Aaron
12/08/2026	Routine maintenance, cleaned 2 plasma heads, clean out plasma source, chiller lines flush + add new coolant 10L. Clean and grease bearings, rails, and racks. Need to get range of spare grease nipples as some missing. More brake clean for jobs ideal GGE - GGE FICEP Robot	08:25:00 07:35:00 - 16:00:00	Aaron