Transition map

State Transitions

Sensor states

L := Left Sensor
M := Mid Sensor
R := right Sensor
ON := ON black line
OFF := Off black line





Left
Right

Assumption: This doesn't occure?!

modules:

main fsm iesmotors iesusart iesadc