

4-2 Adjustment and Application

The following description of adjustment and application take MS300 and CP2000 as examples.

4-2-1 Take MS300 as Example

The followings are abbreviations for different types of motors:

- IM: Induction motor
- PM: Permanent magnet synchronous AC motor
- IPM: Interior permanent magnet synchronous AC motor
- SPM: Surface permanent magnet synchronous AC motor

4-2-1-1 Permanent-Magnet Synchronous Motor, Space Vector Control Adjustment

Procedure (PM SVC, Pr.00-11 = 2)

- PMSVC Control Diagram

