

12

12.1 Service

When you are unable to troubleshoot the robot error(s), use the **Service** page to contact the manufacturer for assistance.

Menu << Information of Customer Service

Location Taiwan E-Mail Robot.Services@Deltaww.com

Product Advisory

Name fish Wang Controller SN. DCS-1D00

Company Delta Telephone (02)12345678#147

Robot Model DRS40L Robot SN. DRS40L3SS1BN002

E-Mail fish@deltaww.com

Subject Communication problem

Mail Body Robot can't link to PLC

Controller Info


Controller Info
DRASudio:V1.00.07.41
FirmwareMain: 1
FirmwareSub: 4
ControllerDSP: 0.0000
DriverDSPMain: .000
DriverDSPSub: 0
LibraryMain: 0

Attach File C:\Delta Industrial Automation\DELTA_IA-Robot_DRASudio-V1-00-07-41_SW_TSE_20210428\DROEbackup\feedt Collect Browse Send


Menu

PC Project : None Execution Status : Close

1. Enter your location, contact information, model numbers, and a description of the issues.
 - In the Controller SN. field, enter the model number on the nameplate of the controller.



- In the Robot SN. field, enter the model number on the nameplate of the robot.



2. Click **Collect**, and the software automatically retrieves the controller information.
3. Click **Browse** to select and attach a compressed file of related information such as the alarm history or the controller backup.
4. Click **Send**, and the PC generates an Outlook email for sending. If not using the Outlook system, you can copy the auto-generated email content and send it using other email systems.