


2.3.4 Tool frame mode



- When switched to Tool frame mode, the robot moves in the directions of the current Tool Frame. As shown in the following figures, once the end of the robotic arm rotates, the Tool Frame rotates as well.

