

4.3	Point data	4-15
4.3.1	JRC (Joint Rotation Count)	4-16
4.3.2	JRC_Active (axis rotation mode)	4-17
4.4	Local points	4-22
4.5	Global points	4-22
4.6	User Frame	4-23
4.6.1	How to teach the User Frame	4-25
4.7	Tool Frame	4-28
4.7.1	Teaching the tool size	4-31
4.7.2	How to teach the tool size	4-33
4.7.3	Teaching the Tool Frame directions	4-37
4.7.4	How to teach the Tool frame directions	4-39
4.8	Work Space	4-42
4.8.1	How to teach a rectangular workspace	4-45
4.8.2	How to teach a cylindrical workspace	4-50

5

Program (RL)

5.1	Function bar	5-3
5.1.1	Compile	5-4
5.1.2	Comment (Add a comment)	5-5
5.1.3	Uncomment (Delete a comment)	5-5
5.1.4	Search/Replace	5-6
5.1.5	Teach (Quick Teach)	5-7
5.2	Program editing	5-8
5.2.1	Debugging	5-8
5.2.2	Variable monitoring	5-9
5.3	RL shortcut key	5-10
5.4	Output panel	5-11

6

I/O control (I/O)

6.1	System IO	6-2
6.1.1	System DI	6-5
6.1.2	System DO	6-9
6.2	User IO	6-12
6.3	Remote IO	6-15
6.4	MonitorAddress (Memory address mapping)	6-17