




(Figure 2-7: PQC-HMI-F10 Left and Right Sides)

| No. | Item                                  | Description                                                                              |
|-----|---------------------------------------|------------------------------------------------------------------------------------------|
| ①   | RTU                                   | RTU communication ports.                                                                 |
| ②   | USB1<br>USB2                          | The USB communication ports.                                                             |
| ③   | LAN                                   | The standard Ethernet port for the communication with the master computer..              |
| ④   | EXTERNAL<br>(Communication Terminals) | For the external RS485 and RS232 signals and the communication with the master computer. |



**NOTE:**

1. Except for the dry contacts and wet contacts, other terminals are insulated. Contacting these terminals will not cause the risk of electric shock.
2. Specifications of the dry contacts and wet contacts are as follows.

| No. | Item                  | Description           |
|-----|-----------------------|-----------------------|
| ①   | OUTPUT (Dry Contacts) | 250 Vac/ 30 Vdc, 2.5A |
| ②   | INPUT (Wet Contacts)  | 24V, 10 mA            |