


4.7.3 Teaching the Tool Frame directions

You can define the X, Y, and Z axis directions of the Tool Frame for different end effectors through teaching.



Tool Frame directions by default and after rotation

- Roll (RX): rotation about the X axis based on the Tool frame of each robot model.
- Pitch (RY): rotation about the Y axis based on the Tool frame of each robot model.
- Yaw (RZ): rotation about the Z axis based on the Tool frame of each robot model.