

- Go to the **JOG** subpage to perform jogging of the robot.

**Setting**

Mode : User

UF: 0 TF: 0

Distance : Max [mm]/[deg.]

☒ Continuous

**Posture**

H: 1 JRC4: 0

**Operator**


X: 255.903 mm

Y: -399.955 mm

Z: -58.972 mm RZ: -125.065 deg

Navigation buttons: Up, Down, Left, Right, Z, RZ

5. Move the robot to the target position.



- Click the **Teach** button in the bottom.

Local

|        | Check                               | Name  | X (mm) | Y (mm) | Z (mm) | RZ (degree) | Hand | UserID | ToolID | Coordinate | CoordinateStr | J4_JRC | JRC_Active |
|--------|-------------------------------------|-------|--------|--------|--------|-------------|------|--------|--------|------------|---------------|--------|------------|
| ▶ 1001 | <input checked="" type="checkbox"/> | p1001 | 0.000  | 0.000  | 0.000  | 0.000       | 0    | 0      | 0      | 1          | User          | 0      | 4          |
| 1002   | <input type="checkbox"/>            | p1002 | 0.000  | 0.000  | 0.000  | 0.000       | 0    | 0      | 0      | 1          | User          | 0      | 4          |
| 1003   | <input type="checkbox"/>            | p1003 | 0.000  | 0.000  | 0.000  | 0.000       | 0    | 0      | 0      | 1          | User          | 0      | 4          |
| 1004   | <input type="checkbox"/>            | p1004 | 0.000  | 0.000  | 0.000  | 0.000       | 0    | 0      | 0      | 1          | User          | 0      | 4          |
| 1005   | <input type="checkbox"/>            | p1005 | 0.000  | 0.000  | 0.000  | 0.000       | 0    | 0      | 0      | 1          | User          | 0      | 4          |

Local Point

Add

Clear

Delete

Save

Motion Command(mm)

Please choose one point

File:

Local

Teach

☐ Check All

Name:

p1001

Motion:

MovP

Ext Teach

Go

Maximum Top

0

Rise height

0

Drop height

0