UB1

FH1: Fuse holder, MF-563

J1: Omron USB-A connector

J2: XHP horizontal 4P host

UB1: Bare board 11x11P



