F1: Fuse SBL32

J1: Omron USB-A connector

J2: XHP horizontal 4P host

UB1: Bare board 10x10P



