;Write a program to count the no of bits that are 1 in register A.

MVI B,0ABH ;Put your number here MVI C,00H MVI D,08H

**LOOP: MOV A,B** 

RLC

CC L1

**MOV B,A** 

L2: DCR D

**MOV A,D** 

**CPI 00H** 

JNC L3

L1: INR C

**RET** 

L3: JZ L4 JNZ LOOP

;Answer is at C

L4: HLT

;Write a program to count the no of bits that are 1 in register A.

MVI A,0AFH ;Put your number here MVI C,00H

RLC;1

CC L1

RLC;2

CC L1

RLC;3

CC L1

RLC;4

CC L1

RLC;5

CC L1

RLC;6

CC L1

RLC;7

CC L1

RLC;8

CC L1

JMP L2

L1: INR C

RET

;Answer is at C

L2: HLT