;Load 1A, 2B, 3C, 4D, 5E, 6F and 7A to the accumulator, register B, C, D, E, H and L respectively. Examine the content of each register before and after the execution of each instruction. (Use MVI instruction)

MVI A,1AH

MVI B,2BH

MVI C,3CH

MVI D,4DH

MVI E,5EH

MVI H,6FH

MVI L,7AH

HLT