;Write a program to rotate the data 3C in port A. Call a delay subroutine for the delaying.

MVI B,3CH MVI D,08H

LOOP: MOV A,B

RLC NOP

**OUT 40H** 

CC L1

**MOV B,A** 

L2: DCR D

**MOV A,D** 

CPI 00H

JNC L3

L1: INR C

**RET** 

L3: JZ L4 JNZ LOOP

L4: HLT