;Convert the problem no 2 for 16-bit numbers.

.MODEL SMALL .STACK 64 .CODE

MOV BX,0000H MOV DI,300H MOV [DI],9FFFH MOV [DI+2],8EEEH

MOV DI,300H MOV AX,[DI] ADD DI,02H ADD AX,[DI] JNC TE INC BX

TE: ADD DI,02H MOV [DI],AX ADD DI,02H MOV [DI],BX MOV AH,4CH INT 21H

END