;Write an assembly language program to sum numbers from 0 to 255.

.MODEL SMALL .STACK 64 .CODE

MOV BX,0000H MOV CX,00FFH MOV AX,0000H

AGAIN: INC BX
ADD AX,BX
LOOP AGAIN
MOV AH,4CH
INT 21H

END