;Write an assemble language program in DEBUG to add four 16-bit numbers and test it.

.MODEL SMALL .STACK 64 .CODE

MOV AX,0A001H; Put your first numer here MOV BX,10AAH; Put your second numer here MOV CX,22FEH; Put your third numer here MOV DX,2291H; Put your fourth numer here

CLC

ADD AL,BL ADC AH,BH

**CLC** 

ADD AL,CL ADC AH,CH

CLC

ADD AL,DL ADC AH,DH

MOV BX,AX; Answer is in BX

MOV AH,4CH INT 21H END