;Write a program to check the bit D5 of the content of memory at 9025. Display 1 at port A if the bit is 1 else displays nothing. Use the rotating instructions after masking. Use the rotating instruction which uses less no of instructions.

**MVI A,79H** 

STC

CMC

RAL;D5

RAL; Rotating 3 times so that it comes at palce of carry

**RAL** 

JNC IS\_LOW; If D5 is low carry is low

MVI A,01H OUT 40H

IS\_LOW: HLT

HLT