;Write an assembly language program that takes a string (having 24 characters at max.) from the user and display each character at the center of each line.

.MODEL SMALL
.DATA
STRLEN DB 24
STRSZ DB ?
STR DB 24 DUP('\$')
STRTRM DB '\$'
.STACK
.CODE

MAIN PROC FAR MOV AX, @DATA MOV DS, AX

;; READING STRING LEA DX, STRLEN MOV AH, 0AH INT 21H

;; CLEARING THE SCREEN MOV AH, 00H MOV AL, 03H INT 10H

;; DISPLAYING IN THE CENTER ;; SETTING CURSOR POSITION LEA SI, STR MOV CH, 00 MOV CL, STRSZ MOV DX, 00H

L1: MOV BH, 00H MOV DL, 40 MOV AH, 02H INT 10H ;; DISPLAYING IN CURSOR POSITION MOV DL, [SI] MOV AH, 02H INT 21H INC DH INC SI LOOP L1

;; ENDING THE PROGRAM MOV AX, 4C00H INT 21H

MAIN ENDP END MAIN