;Load AABB, CCDD and EEFF into register pair BC, DE and HL respectively. Examine the content of each register before and after the execution of each instruction. (Use LXI instruction)

LXI B,0AABBH LXI D,0CCDDH LXI H,0EEFFH HLT