Rotation matrices AE 4532

```
clc
close all
clearvars
rots = [3 1 3];
initial = [2.347; 8.453; 7.916];
total_rot = initial;
ps = deg2rad(40);
th = deg2rad(65);
ph = deg2rad(160);
angle_vec = [ps th ph];
i=1;
for j=rots
    if j == 1
        inter_rot = Rx(angle_vec(i));
    elseif j == 2
        inter_rot = Ry(angle_vec(i));
    elseif j == 3
        inter_rot = Rz(angle_vec(i));
    end
    total_rot = inter_rot*total_rot;
    i = i+1;
end
final_vec = total_rot
function R1=Rx(ph)
    R1 = [1 \ 0 \ 0;
          0 cos(ph) sin(ph);
          0 -sin(ph) cos(ph)];
end
function R2=Ry(th)
    R2 = [\cos(th) \ 0 \ -\sin(th);
          0 1 0;
          sin(th) 0 cos(th)];
end
function R3=Rz(ps)
    R3 = [\cos(ps) \sin(ps) 0;
         -sin(ps) cos(ps) 0;
         0 0 1];
end
```

Published with MATLAB® R2021b