Required Components:

Hardware:

- Resistors, Jumper wires
- Arduino Uno
- Potentiometer (Instead of gas sensor as it is not available in Tinkercad)
- Potentiometer (Instead of gas sensor as it is not available in Tinkercad)
- Piezo Buzzer
- LED
- DC Motor
- In kicad we also use:
- 5v power supply
- PWR flag

Software:

- Tinkercad
- Kicad (for Schematic ,PCB layout and Gerber files)
- Github