

INPUT BIAS CURRENT

I _B	Input bias current	OP07C		±1.8	nA
			T _A = 0°C to 70°C	±2.2	
		OP07D		±12	
			T _A = 0°C to 70°C	±14	
	Input bias current drift	OP07C		±18	pA/°C
		OP07D		±50	
I _{OS}	Input offset current	OP07C		±0.8	nA
			T _A = 0°C to 70°C	±1.6	
		OP07D		±6	
			T _A = 0°C to 70°C	±8	
	Input offset current drift	OP07C		12	pA/°C
		OP07D		±50	