GLPC

SHIFT OPERATIONS • REPORT

NIGHT SHIFT

Sun, 29 Mar 2026

SUMMARY METRICS

38	7 min	0	0	5	373
TOTAL EXCEPTIONS	AVG. SOLVE TIME	PARTS REPLACED	STATUS CHANGES	ROBOTS OFFLINE	ROBOTS ONLINE

OFFLINE ROBOTS LIST

5 total

#	Updated	Number	Type	Issue
1	03/23 17:58	22	A42T	Always has problem with take a box, probably problem with sensor
2	03/19 05:03	528	K50H	chassis drive failure cannot be recovered
3	03/25 08:20	545	K50H	Always has speed error
4	03/28 05:15	426	K50H	front lidar failure
5	03/27 23:02	604	K50H	Robot not response on ping, need to change main border on new one

EMPLOYEE PERFORMANCE

1 technicians

Employee	Exceptions	Total Solve (min)	Avg per Exception (min)	Workload
Andrii Kyrychok	38	256	7	100%

EXCEPTION LOG

All 38 records

Robot	Device	Error Type	Recovery Action	Solve (min)	Start
614	K50H	环境Environment	Move on another QR Code robot then recovery robot, reprinted QR for problem spot	6	18:21
1	A42T	设备Equipment	Adjust position of tote and recovery robot	8	18:21
628	K50H	环境Environment	Move on another QR Code robot then recovery robot, reprinted QR for problem spot	6	18:22
555	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	18:28
468	K50H	设备Equipment	Adjust position of tote and recovery robot	8	18:29
530	K50H	环境Environment	Move on another QR Code robot then recovery robot, reprinted QR for problem spot	6	18:30
545	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	19:14
28	A42T	设备Equipment	Adjust position of tote and recovery robot	8	19:18
587	K50H	设备Equipment	Adjust position of tote and recovery robot	8	19:20
581	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	19:20

Robot	Device	Error Type	Recovery Action	Solve (min)	Start
19	A42T	设备Equipment	Move on QR Code robot then recovery robot	6	19:27
669	K50H	环境Environment	Clean ground code thoroughly	6	19:32
2003	K50H	设备Equipment	Adjust position of tote and recovery robot	8	19:54
13	A42T	设备Equipment	Move on QR Code robot then recovery robot	6	19:57
651	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	20:00
667	K50H	设备Equipment	Adjust position of tote and recovery robot	8	20:04
25	A42T	设备Equipment	Adjust position of tote and recovery robot	8	20:06
32	A42T	设备Equipment	Move on QR Code robot then recovery robot	6	20:07
628	K50H	设备Equipment	Adjust position of tote and recovery robot	8	20:16
427	K50H	环境Environment	Clean ground code thoroughly	6	21:30
692	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	21:49
23	A42T	设备Equipment	Move on QR Code robot then recovery robot	6	23:45
580	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	23:54
408	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	00:26
2026	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	00:27
580	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	00:49
422	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	02:02
441	K50H	设备Equipment	Adjust position of tote and recovery robot	8	02:03
566	K50H	设备Equipment	Adjust position of tote and recovery robot	8	02:03
144	A42T E2	设备Equipment	Adjust position of tote and recovery robot	8	02:17
455	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	02:33
15	A42T	设备Equipment	Move on QR Code robot then recovery robot	6	02:35
54	A42T	设备Equipment	Move on QR Code robot then recovery robot	6	03:33
552	K50H	设备Equipment	Adjust position of tote and recovery robot	8	03:34
692	K50H	设备Equipment	Move on QR Code robot then recovery robot	6	04:15
554	K50H	环境Environment	Move on another QR Code robot then recovery robot, reprinted QR for problem spot	6	04:45
35	A42T	设备Equipment	Adjust position of tote and recovery robot	8	04:48
14	A42T	设备Equipment	Adjust position of tote and recovery robot	8	04:52