

Fix log:

v1: Reversed orientation of the potentiometer

v2: Moved capacitor to ground directly instead of through the LED.

Capacitor value from 10uF to 2.2uF for higher pitch.

v3: Added Keystone 1029 2/3A 12v battery

v4: Adjusted output resistor value from 100k to 22k. Changed battery holder from 2/3A to A23.