



DEPED DRRM

SCHOOL'S SUMMARIZATION OF FIRE SAFETY - BUILDINGS

Name of School: ASINAN ES
School ID: 107137

Name of School Head:
Name of School DRRM Coordinator:

BUILDING NUMBER	BUILDING NAME	NUMBER OF FLOOR	IS THE BUILDING WITH SECONDARY EXIT FOR (2-4 STOREY BUILDING)	NUMBER OF CLASSROOMS	NUMBER OF ROOMS WITHOUT SECONDARY EXIT	NUMBER OF LABORATORIES	NUMBER OF ADMINISTRATIVE OFFICE	NUMBER OF REQUIRED FIRE EXTINGUISHER	NUMBER OF ACTIVE FIRE EXTINGUISHER	SMOKE DETECTOR	ALARMS	REMARKS
01		2	No	3	1	1	1	4	FE 10 FP, FE 04 FR	N/A	ALARM 01 B	
02	Principal's Office	1	N/A	0	0	0	1	0	1	1	ALARM 05 B	
03	03	1	N/A	2	0	0	0	0	FE 03 FR	N/A		
05	05	1	N/A	0	0	0	0	0	FE 11 FP	N/A		CANTEEN, Please clean and clear the area under the water tank
06	USAID BUILDING	2	Yes	15	3	0	0	7	FE 05 FR, FE 06 FR, FE 07 FR, FE 08 FR, FE 09 FR, FE 12 FP, FE 13 FP	N/A	ALARM 02 B, ALARM 03 B	Checking and clearing of grills along the corridor

Prepared by:

Certified Correct:

School DRRM Coordinator

School Head / Principal



DEPED DRRM

FIRE ALARM SYSTEM INSPECTION AND COVERAGE DETAILS

Name of School: ASINAN ES

School ID: 107137

Name of School Head:

DRRM Coordinator:

ALARM CODE	ASSIGNED BUILDING	ALARM TYPE	STATUS	LAST DATE CHECKED	NEXT TEST DUE	REMARKS
ALARM 01	01	Bell	ACTIVE	Apr 15, 2026	May 15, 2026	Please have label
ALARM 02	06 (USAID BUILDING)	Bell	ACTIVE	Apr 15, 2026	May 15, 2026	Please have it labeled
ALARM 03	06 (USAID BUILDING)	Bell	ACTIVE	Apr 05, 2026	May 15, 2026	Please have it labeled and tested regularly
ALARM 05	02 (Principal's Office)	Bell	DEFECTIVE	Apr 15, 2026	May 15, 2026	Have it tested and purchase pull down switch.

Overall Purpose: This sheet is designed for monitoring the alarm's overall coverage of the school, its status, and the type of alarm system installed.

Prepared by:

Noted by:

School DRRM Coordinator

School Head / Principal



DEPED DRRM

FIRE EXTINGUISHER INSPECTION AND COVERAGE DETAILS

Name of School: ASINAN ES

School ID: 107137

Name of School Head:

DRRM Coordinator:

EXTINGUISHER CODE	ROOM COVERED / LOCATION	STATUS	DATE LAST CHECKED	TYPE	REMARKS
FE 01	Principal's Office	ACTIVE	Apr 15, 2026	ABC	Please hang the fire extinguisher and have the label and instructions on how to use FE
FE 03	101 (Room 102 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 15, 2026	ABC	
FE 04	102	FOR PREVENTIVE MAINTENANCE	Apr 15, 2026	HCFC	
FE 05	CLINIC	FOR PREVENTIVE MAINTENANCE	Apr 15, 2026	ABC	
FE 06	102 (Room 103 & Room 104 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 15, 2026	ABC	
FE 07	106 (Room 105 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 15, 2026	ABC	
FE 08	107 (Room 108 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 15, 2026	HCFC	
FE 09	202 (Room 201 & Room 203 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 15, 2026	ABC	
FE 10	LRC	FOR PURCHASE	Apr 15, 2026	ABC	
FE 11	CANTEEN	FOR PURCHASE	Apr 15, 2026	ABC	For further inspection
FE 12	205 (Room 204 & Room 206 taking cover)	FOR PURCHASE	Apr 15, 2026	ABC	
FE 13	208 (Room 207 taking cover)	FOR PURCHASE	Apr 15, 2026	ABC	

Overall Purpose: This sheet is designed for equipment-level tracking, allowing monitoring of maintenance schedules, operational readiness, placement coverage, and compliance documentation.

Prepared by:

Approved by:

School DRRM Coordinator

School Head / Principal



DEPED DRRM

BUILDING ROOM DETAILS & COVERAGE

Name of School: ASINAN ES

School ID: 107137

ROOM INFORMATION

#	ROOM CODE	ROOM NAME	BUILDING	FLOOR	ROOM TYPE	2ND EXIT	SMOKE DETECTOR	COVERED BY	REMARKS
1	102	102	01	1	Classroom	Yes	N/A	FE 04 (Center)	With more than the standard number of Electric Fans 5 and Industrial Fan 1
2	101	LRC	01	1	Laboratory	Yes	N/A	FE 10 (Center)	More than the standard number of Electric Fan 5 and Industrial Fan 2
3	201	201	01	2	Classroom	Yes	N/A	Uncovered	With more than the standard number of Electric Fans 5
4	202	202	01	2	Classroom	Yes	N/A	Uncovered	With more than the standard number of Electric Fans 7
5	203	Guidance Office	01	2	Administration	No	N/A	Uncovered	With more than the standard number of Electric Fans
6	101	Principal's Office	02 - Principal's Office	1	Administration	Yes	Yes	FE 01 (Center)	Provision for Smoke detectors
7	101	101	03 - 03	1	Classroom	Yes	N/A	FE 03 (Center)	With more than the standard number of Electric Fans 7 and avoid octopus connection
8	102	102	03 - 03	1	Classroom	Yes	N/A	FE 03	With more than the standard number of Electric Fans 6
9	101	CANTEEN	05 - 05	1	Canteen	Yes	N/A	FE 11 (Center)	—
10	102	102	06 - USAID BUILDING	1	Classroom	Yes	N/A	FE 06 (Center)	With more than the standard number of Electric Fans 5 and 1 Industrial Fan
11	103	103	06 - USAID BUILDING	1	Classroom	Yes	N/A	FE 06	With more than the standard number of Electric Fans 7
12	104	104	06 - USAID BUILDING	1	Classroom	Yes	N/A	FE 06	With more than the standard number of Electric Fans 5 and removal of Defective Electric fans and Extension Chord
13	105	105	06 - USAID BUILDING	1	Classroom	Yes	N/A	FE 07	With more than the standard number of Electric Fans 5
14	106	106	06 - USAID BUILDING	1	Classroom	Yes	N/A	FE 07 (Center)	—

#	ROOM CODE	ROOM NAME	BUILDING	FLOOR	ROOM TYPE	2ND EXIT	SMOKE DETECTOR	COVERED BY	REMARKS
15	107	107	06 - USAID BUILDING	1	Classroom	Yes	N/A	FE 08 <i>(Center)</i>	With more than the standard number of Electric Fans 6 and 1 Industrial Fan
16	108	108	06 - USAID BUILDING	1	Classroom	No	N/A	FE 08	With more than the standard number of Electric Fans 7
17	101	CLINIC	06 - USAID BUILDING	1	Clinic	Yes	N/A	FE 05 <i>(Center)</i>	—
18	201	201	06 - USAID BUILDING	2	Classroom	No	N/A	FE 09	With more than the standard number of Electric Fans 5
19	202	202	06 - USAID BUILDING	2	Classroom	Yes	N/A	FE 09 <i>(Center)</i>	With more than the standard number of Electric Fans 6
20	203	203	06 - USAID BUILDING	2	Classroom	Yes	N/A	FE 09	With more than the standard number of Electric Fans 6
21	204	204	06 - USAID BUILDING	2	Classroom	Yes	N/A	FE 12	With more than the standard number of Electric Fans 5
22	205	205	06 - USAID BUILDING	2	Classroom	Yes	N/A	FE 12 <i>(Center)</i>	With more than the standard number of Electric Fans 5
23	206	206	06 - USAID BUILDING	2	Classroom	Yes	N/A	FE 12	—
24	207	207	06 - USAID BUILDING	2	Classroom	Yes	N/A	FE 13	With more than the standard number of Electric Fans 6 Repair electric fan switch
25	208	208	06 - USAID BUILDING	2	Classroom	No	N/A	FE 13 <i>(Center)</i>	With more than the standard number of Electric Fans 5

Prepared by:

Approved by:

School DRRM Coordinator

School Head / Principal



Name of School: ASINAN ES
School ID: 107137

Name of School Head:
DRRM Coordinator:

School-Wide Evacuation Plan (Entire School)

No school-wide evacuation plan has been created yet.

Individual Building Evacuation Plans

No individual building evacuation plans have been created yet.

Overall Purpose: This document serves as the official compilation of evacuation plans and assigned assembly parameters, providing critical action directives during emergencies.

Prepared by:

Noted by:

School DRRM Coordinator

School Head / Principal



