

Print at 100% scale. Place one marker at each known table point.

