Service bulletin SB-500-12

Kessler Werkzeugmaschinen KX-500 machining centre

1 Scope

This bulletin applies to KX-500 machining centres, among them CNC-01 and CNC-02 on line 3. It covers a rise in spindle vibration and temperature.

2 Alarm SP-117

The control raises SP-117, spindle vibration above limit, when the spindle vibration passes the limit. SP-104, spindle temperature high, may follow within the hour. Both point to worn spindle bearings.

3 Replacing the bearings

Fit the angular contact pair BRG-7014-ACD with the spacer, a new front seal SEAL-SPDL-70 and fresh grease GREASE-KLB-2. Run the warm-up cycle and check vibration.

4 Parts

BRG-7014-ACD Spindle angular contact bearing 7014 ACD, one pair

SEAL-SPDL-70 Spindle front seal 70 mm, one

GREASE-KLB-2 Spindle bearing grease 400 g, one tube