
(a) Startup step 0 → 300 RPM (grey band = ±5 %)
Raw speed (RPM)
Time (s)
G014: Kp 3.81, Ki 1.454, α 0.2
(b) Steady state (solid = run 1, dashed = run 2)
Raw speed (RPM)
Time (s)